OREGON CORNER RESTORATION FORM 5 Section Township 3N Range 28E 05-14-02 County Umatilla Date: Corner Designation: 3N28A17 Condition Report Only Not Found Remonumented Unrecorded X Surveyed In Referenced Out Previous Renewals / Surveys, etc. Survey S-156-C set brass capped corner at this point. Monument and Accessories Found: (condition and source) Found brass capped corner as shown below. SKETCH **IB4** DIAGRAM SHRW paddle 1145+60 I84 165 N5 °33 E T4N R28E 54.8 corner S35 S34 S3 | S2 T3NR28E 1980 RR tie S32 °41 'W PLS933 61.6 MONUMENT (S) AND ACCESSORIES SET (Procedures and Description) None. REFERENCES SET: None. Made GPS tie to TRI Station Stanfield East Base. Latitude 45°46'37.55280"N Longitude 119°17'24.76730'W Oregon State Plane Coord. - North Zone Northing 771733.64 8510766.24 587.89 Easting Ortho Height Ellipsoidal Height 518.88 NAD 83 (1991) Location and Comments Compass Declination Surveyors Seal 30 °E From the junction of I84 and Highway 207, go south 0.6 miles. Take a road through a stock yard east 0.1 mile and follow the road along the northerly side of an irrigation ditch northeasterly. Follow this road 2.3 miles to its closest point to I84. REGISTERED PROFESSIONAL LAND SURVEYOR RECEIVED BY: David L. Haddock Firm / Agency Date: Haddock Surveying OREGON JULY 12, 1968 ID L. HADDOCK P. O. Box 1574 Pendleton, OR 97801 (541) 276-2174 Rec'd By:

DAVID L

RENEWS 6-30-03