OREGON CORNER RESTORATION FORM

COUNTY: Umatilla. DATE: 10/05/18

East, W.M CORNER DESIGNATION: J-5, The Northeast corner of Section 18, Township 4 North, Range 33

PREVIOUS RENEWALS/SURVEYS ETC: Corner was originally established by Odell and Lewis, Deputy Surveyors, under Contract No. 110, dated February 7, 1865. Notes state:

Set post corner for Secs. 7, 8, 17 &18. Drove charred stake. Dug pits and raised mound as per instructions

MONUMENT AND ACCESSORIES FOUND: None. Reestablished corner at the intersection of an old fence line running East-West with a field berm extending North.

MONUMENT MARKING DETAIL:

T4N R33E S7 | S8 S18 | S17 2018 ----S8

PLS 1106

marked as shown in Monument Marking Detail MONUMENT SET: Set a 2 3/8" brass cap on 1 1/4 by 30" galvanized iron pipe 30 inches in the ground. Cap

New accessories:

A 5/8" by 24" rebar with red plastic cap bears East, 14.1'. A 5/8" by 24" rebar with red plastic cap bears East, 26.0'. A 5/8" by 24" rebar with red plastic cap bears S 89° W, 13.7'. A 5/8" by 24" rebar with red plastic cap bears S 89° W, 25.4'.

object" signs wired to them. Set steel fence post 1.5' West of corner and attached Witness" sign. Red plastic caps are marked "ORPLS 1106 WAPLS 17372" All rebar accessories have "bearing

LOCATION AND COMMENTS: Corner is located at the intersection of an old East-West fence line with a field berm extending North.

FIRM: Wells Surveying P.O. Box 1696

Pendleton, OR

\4N33J-5

enews O WO

Surveyor's Seal

るれ、文を Z O PROFESSIONAL

08EGON JULY 22, 1977 WILLIAM R. WELLS 1108

Urnatilia County RECEIVED /Surveyor

7000 77 00 02 04 Date: , Š 1480 Z