T 4N, R 38E., W.M.

History of original corner establishment:

Corner was originally established by Frank Campbell under Contract No. 468 dated April 12, 1883. Original notes state:
Set a basalt stone 20 ins. % 15 ins. % 4 ins. 15 ins. in ground with 1 notch on S. and 3 notches on E., from which:
A spruce, 12 ins. diam. bears 8 140 = 178 lks.
A spruce, 12 ins. diam. bears 8 300 = 50 lks.
A spruce, 12 ins. diam. bears 8 400 = 800 lks.
A spruce, 12 ins. diam. bears 8 400 = 800 lks.
A spruce, 12 ins. diam. bears 8 400 = 800 lks.

In a SLO dependent resurvey by Otis Gould in 1939, the original corner stone was found and remonumented with a 2" by 36" irrn bipe set 2" in the ground with a brass cap. New bearing trees were marked as follows: a brune, 8 ins. diam. bears N 21/3° E 40 ks dist. marked 14M R38E S27 BI. 8 pine, 8 ins. diam. bears S 26 i/2° E 38 lks dist. marked 14M R38E S28 BI. 8 bine, 12 ins. diam. bears S 26 i/2° W 55 lks dist. marked 14M R38E S38 BI. 8 pine, 9 ins. diam. bears S 35 i/2° W 55 lks dist. marked 14M R38E S28 BI.

This corner was maintained by Dennis Edwards in 1985, as noted on Certificate Record No. 85-102-R, See Sheet 2 of 2 for a statement of evidence found and established by Edwards.

Corner Code No. V-13 Note: Monument marked as shown below

> T4N R38E S28 S27 S33 S34 1939

Corner No. Compass Declination: 18.0°

Description of corner evidence found:

Found 2 1/2" brass cap on 2 1/2" galvanized iron pipe 6" out of small mound of stone from which:

A 8" down lodge pole pine bears N 42 1/2°E, 26.4' with visible scribes. (1939 bearing tree)
A 8" down lodge pole pine bears S 28 1/2°E, 25.1' with visible scribes. (1939 bearing tree)
A 15" lodge pole pine bears S 57°W, 30.4', with visible scribes on a partly healed blaze. (1939 bearing tree)
A 12" down lodge pole pine bears N 35°1/2 W, 36.3' with visible scribes on under side. (1939 bearing tree)
A 10" lodge pole pine bears N 84°W, 12.3' with visible scribes on a partly healed blaze. (Edwards)
A 9" down alpine fir bears N 24°E, 25.8' with visible scribes on a partly healed blaze. (Edwards)
A 7" alpine fir bears S 64°E, 20.4' with visible scribes on a partly healed blaze. (Edwards)

Description of monument and accessories I established to perpetuate the original location of this corner:

There is a steel fence post 4' West of corner with 54-2 and 54-4 signs attached.

Maintained monument by mounding with earth and stone.

Marked 1 new bearing tree:

A 15" Englemann spruce bears N 56 1/2°E, 24.1' scribed T4N R38E S27 BT.

New bearing tree has a brass washer stamped PLS 1106 nailed to face of blaze. Painted face of blaze and a 6" red band around all bearing trees. All bearing trees have 54-3 signs and 54-4 or 54-9 signs attached.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 22, 1977 WILLIAM R. VELLS 1106

Villa R. Wells

Office of	County of
State of , I hereby certify	that the within instrument was filed in this office
for record on the day of	, 19
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

RECEIVED BY

Umatilla County Surveyor

₩ GPO-798-276

Date 1-92

Rec'd By XX
No. 92-0/-X

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

4N, R 38E., W.M.

History of original corner establishment:

Continued from Page 1...

Certificate Record No. 85-102-R by Edwards states:

At corner 1 round 2 1ron pipe with brass cap stamped as in diagram, from which:

A 8 down lodgepole pine root hole bears N 42 1/4° E 26.4 ft. scribe marks visible.

A 8 down lodgepole pine root hole bears S 28 1/2° E 25.1 ft. scribe marks visible.

SHEET Z OF Z Corner Code No. V-13 Note: Monument marked as shown below

DIAGRAM

TAN R38E S28 S27

533 534 1939

Corner No. Compass Declination: 18.0°

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner:

> REGISTERED PROFESSIONAL LAND SURVEYOR

Wellin R. Wells OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

Office of	County of
State of , I hereby certify th	
for record on the day of	
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

RECEIVED BY

Umatilla County Surveyo.

GPO-798-276