CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T 4N, R 38E., W.M.

None. This corner was established as part of this survey.

Note that a 2" brass cap on a 1" iron pipe, origin unknown, was found near the true corner point but was rejected because it is out of position.

History of original corner establishment:

Corner Code No. X-3
Note: Monument marked as shown below

## DIAGRAM

T4N R38E C1/4 • S31

> 1988 PLS 1106

Corper No. Compass Declination: 19.0°

Description of corner evidence found:

Found, a 2" unrecorded brass cap on a 1" iron pipe, protruding 12" from a stone mound. Origin of the monument is unknown. This monument was rejected because it is considerabily out of position—Bearing S  $20^{\circ}34'$  E 10.7' from the corner position as determined by this survey. The brass cap on the found monument is C 1/4 S31

Description of monument and accessories I established to perpetuate the

original location of this corner:
At the position determined by survey, set a 2 1/2" aluminum cap on a 2 1/2" by 30" aluminum pipe, 15" in the ground and surrounded with a mound of earth and stone.

From the new monument, marked new bearing trees as follows:

A 9" alpine fir bears N 10°1/2 W 48.5' scribed C 1/4 S31 BT. A 11" alpine fir bears S 43°1/2 W 66.5' scribed C 1/4 S31 BT.

Bearing trees have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 and 54-9 and painted face of blaze and a 6" red band around each bearing tree. Set steel fence posts South and West of corner and attached sign 54-2 to both posts and sign 54-9 to one post.

PROFESSIONAL LAND SURVEYOR

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

Office of Survey	County of Umatilla
State of OF I have	rehu certify that the within instrument was filed in this office
for record on the day of	in by Jather Amsberry
(COUNTY OFFICIAL)	(DEPUTY)
1.50	RECEIVED BY

Form R6-7100-57 (9/71)

Umatilla County Surveyor

Date 8-88
Rec'd By

No. 88-43-R

0P0-700-276