OREGON CORNER RESTORATION FORM

Section:

24 & 25 19 & 30

Township:

ip: 5 North

Range:

27 East 28 East of the Willamette Meridian

County:

Umatilla

Date:

January 2024

Corner Indexing Information:

Township 5N Range 28E Corner Code R-1 (Willamette Meridian)
Township 5N Range 27E Corner Code R-25 (Willamette Meridian)

Additional Identifier: Corner common to Sections 19 & 30 (T5N R28E), 24 & 25 (T5N R27E)

Oregon Plane Coordinates: N: 813935.79 E: 8489880.59 Zone: North Order: Second

Datum: NAD83-2011(epoch 2010) Convergence: N00°48'05.61"W Scale Factor: 1.00005310467885

Previous Renewals/Surveys, etc.:

1861: Post, mound, pits, & charred stake (Davenport, General Land Office Contract #101)

1973: Established position by proportionate method, using 1943 GLO brass caps at Z-23 (T5N R27E) and Z-13 to establish Z-1, and a pipe at M-1. (Krumbein, C.S. I-016-C) (PBS note: the GLO brass cap at T5N R27E Z-3 has been shown to be set one chain too far West due to an apparent blunder; we have thus rejected most of the monuments derived from this blunder. We have also rejected the pipe at M-1 in favor of an axle found +/- 15' East of the pipe)

1991: Found & rejected brass cap per C.S. I-016-C; established new position on line between 1" iron rod w/5" timber washer at M-1 and 1972 Staebler brass cap at Z-1 (Edwards, 91-001-B) (PBS notes: we found an axle at M-1 at a location consistent with Edwards' iron rod & washer; he notes this as an axle on C.S. 82-016-A. We have accepted this as being on the range line representing M-1, however, we reject Staebler's brass cap at Z-1 due to its being based on a Gould BC at T5N R27E Z-23 which was apparently set by blunder 1 chain West of its intended position.)

Monument(s) & Accessories Found (Condition & Source):

Found and rejected Krumbein brass cap, which bears N85°53'22"W 31.42 feet from the corner; Edwards brass cap was not found.

Monument Set (Procedures & Description):

Established new positions for corners along range line by single-proportion between Krumbein's 1980 monument at Z-1 and the axle found at M-1. Set 1-1/4" iron pipe with 2-1/2" brass cap 1.4' below gravel road surface.

Monument Detail:

T5N

R27E R28E

S 24 | S 19

S 25 | S 30

2023

PLS 02820

New Accessories: WE SET:

A 5/8" iron rebar with plastic cap stamped "WA19619 OR02820" which bears S50°04'45" W 45.45 feet from the corner; set bearing tag on adjacent power pole;

A 5/8" iron rebar with plastic cap stamped "WA19619 OR02820" which bears S71°57'48"E 72.01 feet from the corner; set bearing tag on adjacent power pole;

A 5/8" iron rebar with plastic cap stamped "WA19619 OR02820" which bears N37°50'14"E 84.87 feet from the corner; set bearing tag on adjacent power pole;

A 5/8" iron rebar with plastic cap stamped "WA19619 OR02820" which bears N37°49'18"W 59.23 feet from the corner; set bearing tag on adjacent power pole.

Stamped RM on the found Krumbein brass cap which bears N85°53'22"W 31.42 feet from the corner.

Location & Comments:

Corner falls in intersection of County Road 1226 and a gravel private road.

Compass Declination:

All accessories tied with State Plane grid bearings.

Firm/Agency: PBS Engineering & Environmental, Inc

5 N. Colville

Walla Walla WA 99362

Witness:

Jace A. Boland

Bob D. Eisele

Surveyor's Seal REGISTERED

PROFESSIONAL LAND SURVEYOR

OREGON
JUNE 30, 1997
GREG E. FLOWERS
02820LS

RENEWS 12/31/2025 1/24/2024

R-1.DOC