OREGON CORNER RESTORATION FORM

SECTION 18 TOWNSHIP 5N RANGE 29E

J-3

COUNTY: UMATILLA

DATE 7/91 Revised 10/91

CORNER DESIGNATION

CONDITION REPORT ONLY NOT FOUND

North 1/4 Corner

RENEWED UNRECORDED

SURVEYED IN

REFERENCED OUT


PREVIOUS RENEWALS/SURVEYS, ETC.

Originally surveyed in 1861 by Davenport under Contract #101. He set post, made mound and drove charred stake.

MONUMENTS & ACCESSORIES FOUND: Condition and Source Nothing found.

MONUMENT DETAIL

SKETCH



MONUMENT SET (PROCEDURES AND DESCRIPTION)

Dug a hole 8" deep to rock and poured 4" concrete cylinder with 3" Brass Disc, stamped as above. (by single proportion) See Co. Survey #91-058-B.

NEW ACCESSORIES From which

A 1/2" x 24" rebar with Alum. tag # 951 Bears. N89° 39' 14"W 107.95 ft. A 5/8" x 30" rebar with Alum. tag #951, 9" above surface Bears. S89° 391 14"E 63.85 feet,

A RR spike stamped #951 Bears. North 14.92 feet,

A steel fence post with witness sign Bears. South 12.00 feet.

A 1" x 30" square steel tubing stamped 951 on South face Bears. South 18.88 ft.

## LOCATION & COMMENTS

Corner lies S16°E 1400 ft. from the outlet of a 2 foot diameter Aqueduct on the rk. P.O.BOX 763, HERMISTON, rim of the Columbia River.

SURVEYOR'S SEAL

COMPASS DEC. FIRM EDWARDS SURVEYING OREGON, 97838

PARTY CHIEF D. EDWARDS

NOTES WITNESS S. BENEFIT

RECEIVED BY

Umatilla County Surveyor

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 18, 1971
G. DENNIS EDWARDS
951