OREGON CORNER RESTORATION FORM **SECTION: 13** TOWNSHIP: 5N RANGE: 29E L-21 DATE: 12/05 **COUNTY: UMATILLA** CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED W1/4 Section 13 UNRECORDED SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC.

Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. In 1949 Stranix found old stake & 2" iron pipe & set a concrete monument.

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

Found 2" brass cap in a 5" concrete monument stamped as detail.

MONUMENT DETAIL

T5N 1/4 14-13 R29E

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT, FEET:

822650.40 8548023.18

MONUMENT SET (PROCEDURES AND DESCRIPTION)

NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 50° 55' 42" E 4.84" A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 3° 14' 39" W 23.17' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 88° 31' 57"W 29.46' A 5/8" x 30" Iron Rebar with plastic cap #951 bears \$ 2° 51' 38"W 20.50'

LOCATION AND COMMENTS

Corner lies approximately 500' North of Hwy 730 approximately 600' West of state truck scales at a fence

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON G. DENNIS EDWARDS

RENEWS 12/31/05

:\Works\Restform\L-5

06-265-C