OREGON CORNER RESTORATION FORM SECTION: 13 TOWNSHIP: 5N RANGE: 29E L-25 DATE: 12/05 COUNTY: UMATILLA CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED E1/4 Section 13 UNRECORDED SURVEYED IN REFERENCED OUT

PREVIOUS RENEWALS/SURVEYS ETC.

Originally surveyed by Payne under Contract # 100 in 1861. He set post and made mound. In 1949 Stranix set a railroad spike in a rock.

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE Nothing found.

MONUMENT DETAIL

T5N R29E R30E 1/4 13 | 18 2005 L.S. 951

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

822670.79 8553237.60

MONUMENT SET (PROCEDURES AND DESCRIPTION)

By single proportion I set a 1"x30" iron pipe with 2 3/8 brass cap stamped as detail, 2" above the surface

NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 84° 40' 04" E 32.29' A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 34° 32' 19" E 22.66' A 5/8 x 30 Iron Rebar with plastic cap #951 bears N 44° 12' 14"W 150.70' A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 60° 11' 00"W 358.84'

LOCATION AND COMMENTS

From intersection of hwy 730 with cold springs hwy go south-easterly on coldsprings hwy 0.9 miles. Corner lies on the right side of highway approximately 30'.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON G. DENNIS EDWARDS

lward

RENEWS 12/31/05

c:\Works\Restform\L-5

06-265-C