OREGON CORNER RESTORATION FORM N-15 SECTION: 22 TOWNSHIP: 5N RANGE: 29E COUNTY: UMATILLA DATE: 12/05 CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED N 1/4 Section 22 UNRECORDED SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. MONUMENTS AND ACCESSORIES FOUND: CONDITON AND SOURCE

MONUMENT DETAIL

Nothing found

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

819842.40 8540156.60

MONUMENT SET (PROCEDURES AND DESCRIPTION)

By single proportion I set a 1"x12" iron pipe in concrete 24" below the surface of a cultivated field.

NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 16° 41' 26" E 566.27' A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 4° 40' 42" E 656.07' A 5/8 x 30 Iron Rebar with plastic cap #951 bears N 14° 53' 34" W 985.89' A 5/8" x 30" Iron Rebar with plastic cap #951 bears N.40° 20' 21" W 1224.98'

LOCATION AND COMMENTS

Corner lies approximately 700 feet Southwest of Hat Rock Trailer Park in a cultivated field.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 16, 1971 G. DENNIS ÉDWARDS 9 5 1

RENEWS 12/31/05

c:\Works\Restform\L-5

06-265-C