# OREGON CORNER RESTORATION FORM **SECTION: 23 TOWNSHIP: 5N** RANGE: 29E N-21 **DATE**: 12/05 COUNTY: UMATILLA CONDITION REPORT ONLY NOT FOUND CORNER DESIGNATION RENEWED NE Section 23 UNRECORDED SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. In 1949 Stranix found old stake in mound of stone. Set concrete monument.

## MONUMENTS AND ACCESSORIES FOUND: CONDITON AND SOURCE

Found 2 5/8" brass cap in a 4" concrete monument stamped as below, 4" above the surface.

### MONUMENT DETAIL

T5N 14 | 13 23 | 24 R29 E

# OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

820021.84 8548116.67

## MONUMENT SET (PROCEDURES AND DESCRIPTION)

#### NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 87° 04' 20" E 45.14' A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 5° 08' 21" W 33.77' A 5/8 x 30 Iron Rebar with plastic cap #951 bears S 89° 26' 41"W 137.78' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 3° 48' 33" E 36.02'

## LOCATION AND COMMENTS

From the truck scales on hwy 730 go South - Southwest 0.4 miles to corner.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 16, 1971
G. DENNIS EDWARDS

Colward

RENEWS 12/31/05

c:\Works\Restform\L-5

06-265- C