OREGON CORNER RESTORATION FORM SECTION:19 TOWNSHIP: 5N RANGE: 29E N-3 DATE: 12/05 COUNTY: UMATILLA CONDITION REPORT ONLY NOT FOUND CORNER DESIGNATION RENEWED UNRECORDED N 1/4 Section 19 SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. MONUMENTS AND ACCESSORIES FOUND: CONDITON AND SOURCE MONUMENT DETAIL T5NR29E 1/4 18 19 2005 L.S. 951 OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET: 819610.90

MONUMENT SET (PROCEDURES AND DESCRIPTION)

By single proportion I set a 1"x 30" iron pipe in concrete with a 2 3/8 " brass cap stamped as above 5" above the surface.

NEW ACCESSORIES FROM WHICH

8524283.12

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 58° 10' 49" E 81.83' A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 28° 59' 05 E" 58.27' A 5/8 x 30 Iron Rebar with plastic cap #951 bears N 13° 01' 26" W 61.86' A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 23° 01' 58" W 68.69'

LOCATION AND COMMENTS

From intersection of Craig Rd. with hwy 730 go west on 730 1/2 mile. corner lies North of highway about 60' South of north R/W fence.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 16, 1971 G. DENNIS EDWARDS 9 5-1

RENEWS 12/31/05

c:\Works\Restform\L-5

06-265-C