OREGON CORNER RESTORATION FORM P-5 RANGE: 29E SECTION:19 TOWNSHIP: 5N COUNTY: UMATILLA DATE: 12/05 CONDITION REPORT ONLY NOT FOUND CORNER DESIGNATION RENEWED UNRECORDED E1/4 Section 19 SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. In 1995 Rogers set an aluminum cap In 1988 Roberts set a 1"x30" iron pipe with a 2 3/8' brass cap MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE Found 2 3/8' brass cap stamped below, 6" below the surface. W.C. 5/8" iron rebar with plastic cap 2627 bears N 30° 45' 29" E 60.55' (60.52') W.C.5/8" iron rebar with plastic cap 2627 bears N 18° 43' 43" W 54.36' (54.33') W.C. 5/8" iron rebar with plastic cap 2627 bears S 40° 24' 51" W 14.41'(14.49') W.C. 5/8" iron rebar with plastic cap 2627 bears S 38° 16' 32" E 11.58' (11.64') MONUMENT DETAIL T5NR29E 1/4 S19 S20 1998 L.S. 2629 OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET: 817010.18 8526962.43 MONUMENT SET (PROCEDURES AND DESCRIPTION) NEW ACCESSORIES FROM WHICH LOCATION AND COMMENTS At the intersectioon of Purdy Rd & Craig Rd. Corner lies South & West of intersection. SURVEYOR'S SEAL FIRM: EDWARDS SURVEYING LLC REGISTERED PROFESSIONAL PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH

LAND SURVEYOR

OREGON G. DENNIS EDWARDS 951

RENEWS 12/31/05

06-265-C