OREGON CORNER RESTORATION FORM P-9 SECTION:20 TOWNSHIP: 5N RANGE: 29E DATE: 12/05 COUNTY: UMATILLA CONDITION REPORT ONLY NOT FOUND CORNER DESIGNATION RENEWED UNRECORDED E1/4 Section 20 SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. MONUMENTS AND ACCESSORIES FOUND: CONDITON AND SOURCE Nothing found MONUMENT DETAIL T5NR29E 1/4 21 2005

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

817024.15 8532278.66

MONUMENT SET (PROCEDURES AND DESCRIPTION)

By single proportion I set a 1"x12" iron pipe in concrete with a 2 3/8" brass cap stamped as above. 25" below the surface is a cultivated field.

NEW ACCESSORIES FROM WHICH

951

A concrete nail in a pivot pad bears N 48° 08' 42" E 240.97'
A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 86° 23' 08" E 239.39'
A 5/8 x 30 Iron Rebar with plastic cap #951 bears S 74° 42' 01" E 235.56'
A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 60° 22' 31" E 250.44'

LOCATION AND COMMENTS

1.0 mile East of the intersection of Craig Rd. and hwy 730. Corner lies about 700' South of hwy 730 & 240' SW of center pivot.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 16, 1971 G. DENNIS EDWARDS 9 5 1

RENEWS 12/31/05

c:\Works\Restform\L_5

06-265-C