OREGON CORNER RESTORATION FORM R-15 RANGE: 29E SECTION:27 TOWNSHIP: 5N **COUNTY: UMATILLA DATE**: 12/05 CONDITION REPORT ONLY NOT FOUND CORNER DESIGNATION RENEWED N1/4 Section 27 UNRECORDED SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. MONUMENTS AND ACCESSORIES FOUND: CONDITIN AND SOURCE Nothing found MONUMENT DETAIL T5NR2E 1/4 22 27 2005 L.S. 951 OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET: 814562.45 8540253.07 MONUMENT SET (PROCEDURES AND DESCRIPTION) By single proportions I set a 5/8"x30" iron rebar with a 2" aluminum cap stamped as above at the surface of a paved road.

NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears S $46^{\circ}24'$ 58" E 24.47' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 30° 32' 47" W 19.98' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 62° 28' 30" W 36.01' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 81° 24' 42" W 115.77'

LOCATION AND COMMENTS

From the intersection of Tabor road with Progress road, go East on Progress 0.5 miles to corner.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 16, 1971 G. DENNIS EDWARDS 9 5 1

RENEWS 12/31/05