OREGON CORNER RESTORATION FORM R-23 TOWNSHIP: 5N RANGE: 29E SECTION:25 COUNTY: UMATILLA DATE: 12/05 CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED N1/4 Section 25 UNRECORDED SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE Nothing found.

MONUMENT DETAIL

T5NR29E

1/4 24

25

2005

L.S. 951

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

814731.83 8550814.21

MONUMENT SET (PROCEDURES AND DESCRIPTION)

By single proportion I set 1"x12" iron pipe in concrete 25" below the surface of a cultivated field stamped as above.

NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 44° 03' 42" E 417.31'

A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 65° 58' 35" W 632.15'

A 5/8 x 30 Iron Rebar with plastic cap #951 bears S 41° 13' 32" W 1217.82'

A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 76° 57' 57" E 1738.59'

A conc. nail in pivot pad bears S 28° 32' 27" E 932.24'

LOCATION AND COMMENTS

From the intersection of Cold Springs highway with Walls road go Southwesterly along Walls road 1.3 miles. Then go Westerly between pivots 0.6 miles. Corner lies about 930' NW of the center pivot.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 16, 1971
G. DENNIS EDWARDS
9 5 1

RENEWS 12/31/05

c-\Works\Restform\L-5