OREGON CORNER RESTORATION FORM

PREVIOUS RENEWALS/SURVEYS ETC.

Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. In 1910 Kimbrell set 2" iron pipe.

In 1991 Edwards set a 1"x 3" iron pipe in concrete with a 2 3/8" brass cap over the 2" iron pipe.

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

Found 2 3/8" brass cap 12" below the surface of a road. Stamped as below. W.C. an alum. tag 951 in a RR tie fence post bears N 71° 41' 13" E 51.12' (51.46')

W.C. an alum. tag 951 in a RR tie fence post bears N 71 41 15 E 51.12 (51.40)

MONUMENT DETAIL

L.S. 951

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

814376.09 8527006.38

MONUMENT SET (PROCEDURES AND DESCRIPTION)

NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 4° 29' 16" W 48.05' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 59° 06' 25" E 50.47'

LOCATION AND COMMENTS

At the intersection of Craig Rd & Progress Rd.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

lward

OREGON JULY 16, 1971 G. DENNIS EDWARDS 9 5 1

RENEWS 12/31/ 05

c:\Works\Restform\L_5

06-265-C