OREGON CORNER RESTORATION FORM

SECTION:29 TOWNSHIP: 5N

RANGE: 29E

R-7

COUNTY: UMATILLA

DATE: 12/05

CORNER DESIGNATION

___CONDITION REPORT ONLY ___NOT FOUND

N 1/4 Section 29

X_RENEWED

___UNRECORDED

X SURVEYED IN

___ REFERENCED OUT

PREVIOUS RENEWALS/SURVEYS ETC.

Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. In 1910 Kimbrell set iron pipe.

In 1979 LaGier set a 5/8" iron rebar. It was 8' North & 26.6" West.

In 2000 Roberts set a 5/8" iron rebar by single proportions.

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

Found 5/8" iron rebar with a 2" aluminum cap 4" below the surface stamped as below. See Monument Set.

W.C. found 5/8" iron rebar with plastic cap 2627 bears N 13° 43' 46" E 85.17'(85.20')

W.C. found 5/8" iron rebar with plastic cap 2627 bears N 35° 32' 16" W 111.86'(111.88')

W.C. found 5/8" iron rebar with plastic cap 2627 bears N 74° 51' 13" W 28.22'

W.C. found 5/8" iron rebar with plastic cap 2627 bears N 89° 14" 51" W 49.97'(50.00')

W.C. found 5/8" iron rebar with plastic cap 2627 bears N 89° 14' 30" W 99.99'(100.00')

MONUMENT DETAIL

T5NR29E 1/4 S20 S29 2000 P.L.S. 2627

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

814382.98 8529664.71

MONUMENT SET (PROCEDURES AND DESCRIPTION)

Monument has been disturbed.

Moved it N 60° W 0.31 feet, drove to 6 " below surface and poured concrete around.

NEW ACCESSORIES FROM WHICH

LOCATION AND COMMENTS

From the intersection of Craig Rd. with Progress road. Go East 0.5 miles along a dirt road to corner.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 16, 1971 G. DENNIS EDWARDS 9 5 1

RENEWS 12/31/05

c:\Works\Restform\L_5

06-265-C