# OREGON CORNER RESTORATION FORM SECTION:29 TOWNSHIP: 5N R-9 RANGE: 29E COUNTY: UMATILLA DATE: 12/05 CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED NE Section 29 UNRECORDED SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. In 1910 Kimbrell set 2" Iron pipe. County survey # 308 MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE Found 2" iron pipe 11" below the surface. MONUMENT DETAIL

## OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

814389.88 8532323.05

#### MONUMENT SET (PROCEDURES AND DESCRIPTION)

### NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 89° 41' 16" E 34.70' A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 77° 48' 20" E 99.10' A 5/8 x 30 Iron Rebar with plastic cap #951 bears N 64° 34' 17" E 87.95' A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 0° 01' 52" W 133.33'

#### LOCATION AND COMMENTS

From the intersection of Golda road with Progress road. Go West 0.5 miles to corner along a dirt road.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 16, 1971
G. DENNIS EDWARDS
9 5 1

RENEWS 12/31/05

c:\Works\Restform\L.5

06-265-C

Leverds