OREGON CORNER RESTORATION FORM RANGE: 29E T-21 SECTION:25 TOWNSHIP: 5N COUNTY: UMATILLA DATE: 12/05 CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED UNRECORDED W1/4 Section 25 SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC.

Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound.

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE Nothing found.

MONUMENT DETAIL

T5NR29E

1/4

26 | 25

2005

L.S. 951

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

812065.61 8548221.43

MONUMENT SET (PROCEDURES AND DESCRIPTION)

By single proportion I set a 1"x12" iron pipe in concrete with a 2 3/8" brass cap 25" below the surface of a cultivated field.

NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 38° 47' 27" E 660.10'

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 16° 44' 52" E 887.62'

A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 53° 44' 23" W 493.66'

A concrete nail in a pivot pad bears N 36°34' 05" W 514.92'

LOCATION AND COMMENTS

From an angle point in Walls road go Northerly around a large pivot 0.7 miles. Corner lies in a half circle Southeast 515 feet from the pivot pad.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH

REGISTERED **PROFESSIONAL** LAND SURVEYOR

G. Denni Elwade

OREGON G. DENNIS EDWARDS

RENEWS 12/31/05

06-265-C