OREGON CORNER RESTORATION FORM T-5 RANGE: 29E SECTION:30 TOWNSHIP: 5N **DATE**: 12/05 COUNTY: UMATILLA CONDITION REPORT ONLY NOT FOUND CORNER DESIGNATION RENEWED UNRECORDED E1/4 Section 30 SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound.

In 1910 Kimbrell set 1 1/2" iron pipe.

In 1992 Edwards drove a 1/2" iron rebar into Kimbrells iron pipe.

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

Found a 1/2" iron rebar in concrete 3" below the surface of a paved road.

MONUMENT DETAIL

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

811736.90 8527052.92

MONUMENT SET (PROCEDURES AND DESCRIPTION)

NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 65° 21' 46" E 36.26'

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 38° 29' 24" W 45.75'

A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 15° 17' 32" W 121.68'

A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 26° 46' 36" E 41.48'

LOCATION AND COMMENTS

At the intersection of Craig and Spearman road.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH

REGISTERED **PROFESSIONAL** LAND SURVEYOR

ward OREGON G. DENNIS EDWARDS 951

RENEWS 12/31/05

010-265-C