OREGON CORNER RESTORATION FORM T-9 SECTION:29 TOWNSHIP: 5N RANGE: 29E **DATE**: 12/05 COUNTY: UMATILLA CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED UNRECORDED E1/4 Section 29 SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. In 1978 Krumbein set a 5/8" iron rebar. MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE Found 1 1/2" aluminum cap 2" below the surface of a paved road. Illegible

MONUMENT DETAIL

T5NR29E

1/4

29 | 28

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

811765.24 8532368.26

MONUMENT SET (PROCEDURES AND DESCRIPTION)

NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 19° 13' 42" E 13.69' A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 36° 28' 42" W 27.18' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 73° 44' 52" W 63.86' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 43° 04' 11" E 28.46'

LOCATION AND COMMENTS

At the intersection of Spearman & Edwards roads.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

Leon

OREGON JULY 16, 1971 G. DENNIS EDWARDS 9 5 1

RENEWS 12/31/05

c:\Works\Restform\I_a5

06-265-C