OREGON CORNER RESTORATION FORM SECTION:33 TOWNSHIP: 5N RANGE: 29E V-11 COUNTY: UMATILLA DATE: 12/05 CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED N1/4 Section 33 UNRECORDED SURVEYED IN X REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. In 1913 Kimbrell set a 3" iron pipe. In 1990 Edwards set a 2 1/2" brass disk in concrete over 3" iron pipe. MONUMENTS AND ACCESSORIES FOUND: CONDITON AND SOURCE Found 2 1/2" brass disk at surface of a paved road stamped as below. W.C. a 5/8" iron rebar with plastic cap #951 bears N 44° 45' 43" W 30.43'(30.35') W.C. a 5/8" iron rebar with plastic cap #951 bears S 44° 56' 50" E 26.72'(26.78') W.C. an aluminum tag #951 in a R/R tie bears S 58° 03' 14" W 50.54'(50.50') MONUMENT DETAIL T5NR29E 1/4 28 33 1990 L.S. 951 OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET: 809191.76 8535059.07 MONUMENT SET (PROCEDURES AND DESCRIPTION) NEW ACCESSORIES FROM WHICH A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 76° 31' 53" E 76.05' LOCATION AND COMMENTS At the intersection of Golda road & Walls road. (On Walls Road 1/2 mile East of Edwards road) SURVEYOR'S SEAL REGISTERED PROFESSIONAL FIRM: EDWARDS SURVEYING LLC LAND SURVEYOR PO BOX 763 - HERMISTON OR 97838 Lennin Chevards

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH

OREGON G. DENNIS EDWARDS

RENEWS 12/31/05

:\Works\Restform\L-5

06-265-C