## OREGON CORNER RESTORATION FORM

SECTION:34	TOWNSHIP: 5N		RANGE: 25	9E V-15
COUNTY: UM	ATILLA	DATE:	12/05	
				CONDITION REPORT ONLY
CORNER DESIGNATION				- NOT FOUND
				RENEWED
N1/4 Secti			UNRECORDED	
1127 5001				X SURVEYED IN
				X REFERENCED OUT

#### PREVIOUS RENEWALS/SURVEYS ETC.

Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound.

# MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE Nothing found.

#### MONUMENT DETAIL

T5NR29E 1/4 27 34 2005 L.S.951

## OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

809282.48 8540347.58

### MONUMENT SET (PROCEDURES AND DESCRIPTION)

By single proportion I set a 1"x30" iron pipe in concrete with a 2 3/8" brass cap stamped as above 3" below the surface of a paved road on the South shoulder.

## NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 59° 21' 11" E 63.23' A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 34° 51' 40" W 40.23' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 87° 27' 49" W 222.90' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 77° 50' 31" E 33.62'

#### LOCATION AND COMMENTS

From the intersection of Tabor road with Walls road go East on Walls 0.5 mile to corner.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 16, 1971
G. DENNIS EDWARDS
9 5 1

RENEWS 12/31/05

c:\Works\Restform\La5

06-265-C