## OREGON CORNER RESTORATION FORM V-19 TOWNSHIP: 5N RANGE: 29E SECTION:26 COUNTY: UMATILLA DATE: 12/05 CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED S1/4 Section 26 UNRECORDED SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE Nothing found MONUMENT DETAIL T5NR29E 1/4 26 35 2005 L.S.951 OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET: 809367.32 8545622.11 MONUMENT SET (PROCEDURES AND DESCRIPTION) By single proportion I set a 1"x30" iron pipe in concrete with a 2 3/8" brass cap stamped as above 4" below the surface. NEW ACCESSORIES FROM WHICH A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 84° 37' 14" E 108.43'

A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 84° 37' 14" E 108.43' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 79° 53' 01" W 48.40' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 3° 16' 27" W 9.17' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 80° 48' 30" E 60.10'

## LOCATION AND COMMENTS

From intersection of Marks road with Walls road go East on Walls road 0.5 miles to corner. Corner lies North of north R/W fence.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 16, 1971 G. DENNIS EDWARDS 9 5 1

RENEWS 12/31/05

c:\Works\Restform\L\_5

06-265-C