OREGON CORNER RESTORATION FORM RANGE: 29E V-3 SECTION:31 TOWNSHIP: 5N **COUNTY: UMATILLA DATE**: 12/05 CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED UNRECORDED N1/4 Section 31 SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE Nothing found

MONUMENT DETAIL

T5NR29E

1/4 30

31

2005 L.S. 951

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

809053.94 8524457.02

MONUMENT SET (PROCEDURES AND DESCRIPTION)

By single proportion I set a 1"x25" iron pipe in concrete with a 2 3/8" brass cap stamped as above, 6" below the surface of a graveled road.

NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 29° 17' 13" W 43.77' A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 49° 29' 56" W 29.80' A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 85° 13' 45" W 165.91' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 62° 25' 50" W 26.76'

LOCATION AND COMMENTS

From the intersection of Craig road with Walls road go west on Walls road 0.5 miles to corner.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH

REGISTERED **PROFESSIONAL** LAND SURVEYOR

> OREGON G. DENNIS EDWARDS

RENEWS 12/31/05

06-265-C