# OREGON CORNER RESTORATION FORM V-7 SECTION:32 TOWNSHIP: 5N RANGE: 29E DATE: 12/05 COUNTY: UMATILLA CONDITION REPORT ONLY NOT FOUND CORNER DESIGNATION RENEWED UNRECORDED N1/4 Section 32 SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. In 1979 LaGier used a 5/8" iron rebar which lies 30.64' West of corner. In 1989 Edwards set a 1"x30" iron pipe with 2 3/8" brass cap. MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

W.C. an aluminum tag #951 in a power pole bears S 54° 04' 01" E 29.74'(29.80')

MONUMENT DETAIL

T5NR29E 1/4 29

32

1989

L.S. 951

#### OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

Found a 2 3/8" brass cap 10" below the surface of a graveled road stamped as below. W.C. an aluminum tag #951 in a power pole bears N 32° 46' E 38.51'(38.51')

809120.74 8529756.00

### MONUMENT SET (PROCEDURES AND DESCRIPTION)

#### NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 4° 12' 44" E 35.57' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 68° 57' 25" W 45.61'

## LOCATION AND COMMENTS

From the intersection of Craig road with Walls road go East on Walls 0.5 miles to corner.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 16, 1971 G. DENNIS EDWARDS 9 5 1

RENEWS 12/31/05

c:\Works\Restform\L\_5

06-265-C