OREGON CORNER RESTORATION FORM X-13 SECTION:33 TOWNSHIP: 5N RANGE: 29E COUNTY: UMATILLA DATE: 12/05 CONDITION REPORT ONLY NOT FOUND CORNER DESIGNATION RENEWED UNRECORDED E1/4 Section 33 SURVEYED IN X REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. In 1913 Kimbrell set 2" iron pipe. In 2002 Edwards drove 5/8" iron rebar into 2" iron pipe.

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

Found 5/8" iron rebar 5" below the surface of a graveled road.

W.C. found aluminum tag # 951 in a power pole bears S 56° 06' 32" W 41.38'(41.38')

W.C. found aluminum tag # 951 in a power pole bears S 32° 02' 09" E 28.16'(28.40')

MONUMENT DETAIL

T5NR29E

1/4

33 34

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

806603.24 8537755.66

MONUMENT SET (PROCEDURES AND DESCRIPTION)

NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 45° 42' 03" W 31.43' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 33° 31' 03" E 24.36'

LOCATION AND COMMENTS

At the intersection of Tabor road and Columbia Lane.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON G. DENNIS EDWARDS 951

RENEWS 12/31/05

06-265-C

dwar