## OREGON CORNER RESTORATION FORM SECTION:36 TOWNSHIP: 5N RANGE: 29E X-25 DATE: 12/05 COUNTY: UMATILLA CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED UNRECORDED E1/4 Section 36 SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Payne under Contract # 100 in 1861. He set post and made mound. MONUMENTS AND ACCESSORIES FOUND: CONDITON AND SOURCE Nothing found. MONUMENT DETAIL T5N R29E R30E 1/4 36 | 31 2005 L.S. 951 OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET: 806825.21

## MONUMENT SET (PROCEDURES AND DESCRIPTION)

By single proportion I set a 1"x30" iron pipe with a 2 3/8" brass cap stamped as above 2" above the surface.

## NEW ACCESSORIES FROM WHICH

8553592.17

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 0° 10' 20" W 124.99' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 71° 18' 37" W 37.21' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 0° 26' 28" W 11.44' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 55° 31' 58" E 19.45'

## LOCATION AND COMMENTS

Corner lies 12' North of the National Wildlife Refuge fence.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 16, 1971 G. DENNIS EDWARDS 9 5 1

RENEWS 12/31/05

c:\Works\Restform\L-5

06-265-C