## OREGON CORNER RESTORATION FORM Z-13 SECTION:33 TOWNSHIP: 5N RANGE: 29E **DATE: 12/05** COUNTY: UMATILLA CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED UNRECORDED SE Section 33 SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Maxon & Hurd under Contract # 50 in 1860. They set post and made mound. In 1990 I set a 2 1/2" brass cap in concrete over a 1 1/4" iron pipe of unknown origin. MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE Found 2 1/2" brass cap stamped as below 6" below the surface. W.C. an aluminum tag in a R/R tie bears N 59° E 1.10' W.C. an aluminum tag in a R/R tie bears N 88° 44' 26" E 57.86'(57.86') W.C. a 2 1/2" brass cap bears N 0° 00' 08" W 12.00'(12.00') MONUMENT DETAIL T5NR29E 33 | 34 1990 L.S. 951 OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET: 803962.38 8537802.53 MONUMENT SET (PROCEDURES AND DESCRIPTION) NEW ACCESSORIES FROM WHICH A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 0° 53' 40" E 107.66' LOCATION AND COMMENTS At the fence corner on the Southeasterly projection of Tabor road and the Easterly projection of Punkin Center road.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 16, 1971
G. DENNIS EDWARDS
951

RENEWS 12/31/05

c:\Works\Restform\L\_5

06-265-C