OREGON CORNER RESTORATION FORM Z-7 SECTION:32 TOWNSHIP: 5N RANGE: 29E **DATE**: 12/05 COUNTY: UMATILLA CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED UNRECORDED S1/4 Section 32 SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Maxon & Hurd under Contract # 50 in 1860. They set post and made mound. In 1984 Edwards set 1/2" iron rebar over a 1" bolt. In 1990 Edwards set a 2 1/2" brass cap in concrete over bolt. MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE Found 2 1/2" brass cap in concrete stamped as below flush with the pavement. W.C. an alum. tag #951 in a RR tie fence post bears N 36° 04' 40" W 27.76' (27.94') W.C. an alum. tag #951 in a power pole bears S 42° 40' 57" W 26.91' (26.89') MONUMENT DETAIL T5NR29E S1/4 Sec 32 1990 L.S. 951 OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET: 803859.18 8529835.13 MONUMENT SET (PROCEDURES AND DESCRIPTION) NEW ACCESSORIES FROM WHICH A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 52° 21' 17" W 31.57' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 70° 48' 32" E 63.87' LOCATION AND COMMENTS At the intersection of Punkin Center road with Cabana road.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 16, 1971 G. DENNIS EDWARDS 9 5 1

RENEWS 12/31/05

c-\Works\Restform\L-5

06-265-C