## OREGON CORNER RESTORATION FORM SECTION:32 TOWNSHIP: 5N RANGE: 29E Z-9 **DATE**: 12/05 COUNTY: UMATILLA CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED SE Section 32 UNRECORDED SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Maxon & Hurd under Contract # 50 in 1860. They set post and made mound. In 1913 Kimbrell set 2 1/2" iron pipe. In 1975 Staebler drove 1/2" iron rebar into iron pipe. In 1990 Edwards set a 2 1/2" brass cap over 1/2" iron rebar. MONUMENTS AND ACCESSORIES FOUND: CONDITON AND SOURCE Found 1/2" iron rebar 4" below the surface of a paved road. W.C. an aluminum tag # 951 in a RR tie bears N 23° 06' 31" W 67.62'(69.54') W.C. an aluminum tag # 951 in a power pole bears S 49° 30' 29" E 46.01'(45.96') W.C. an aluminum tag # 951 in a RR tie bears N 48° 25' 04" E 47.43'(47.26') MONUMENT DETAIL T5NR29E 32 | 33 1990 L.S. 951 OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET: 803893.83 8532494.06 MONUMENT SET (PROCEDURES AND DESCRIPTION) NEW ACCESSORIES FROM WHICH A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 1° 23' 45" W 24.37" LOCATION AND COMMENTS At the intersection of Edwards road (North) with Punkin Center road.

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH

SURVEYOR'S SEAL

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON G. DENNIS EDWARDS

RENEWS 12/31/05

06-265-C