OREGON CORNER RESTORATION FORM RANGE: 29E V-25 SECTION:25 TOWNSHIP: 5N **DATE**: 12/05 COUNTY: UMATILLA CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED SE Section 25 UNRECORDED SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Payne under Contract # 100 in 1861. He set post and made mound. MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

T5N R29E R30E 25 | 30

MONUMENT DETAIL

Nothing found.

36 | 31

2005

L.S. 951

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

809465.36 8553541.12

MONUMENT SET (PROCEDURES AND DESCRIPTION)

By single proportion I set a 1"x12" iron pipe in concrete with a 2 3/8" brass cap stamped as above, 25" below the surface of a cultivated field.

NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 84° 31' 21" E 1272.23' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 14° 04' 04" E 1635.77' A 5/8 x 30 Iron Rebar with plastic cap #951 bears S 19° 45' 37" W 1715.63' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 47° 59' 45" W 1723.88'

LOCATION AND COMMENTS

From an angle point in Walls road go East 1.0 miles. Corner lies about 200' Northeast of a center pivot.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 16, 1971 G. DENNIS EDWARDS 9 5 1

RENEWS 12/31/05

c:\Works\Restform\L_5

06-265-C

Luwo