

REGISTERED RECORD OF LAND CORNER MONUMENTATION

T 5N, R 32E., W.M.

Corner Code No. X-5

Note: Monument marked as shown below

History of original corner establishment:

This corner was originally established by Nicholas O. Walden, U.S. Deputy Surveyor, under Contract No. 207, dated July 6, 1874. The original notes state:

Drove charred stake and raised mound of earth, with pits, etc., as per instructions, for 1/4 Sec. Cor.

DIAGRAM

T5N R32E

1/4

S31 | S32

1993

PLS 1106

Corner No.
Compass Declination: 18.0°

Description of corner evidence found:

Found old fence intersection, with fence remains extending South and West.

Original topo call of 3.5 chains to North Cold Springs Creek fits well.

County Road Notes for County Road No. 887, indicate a stone for the corner, 528 feet North of the centerline of the Road. The corner area has been worked over and a stone was not found. The distance from the existing County Road centerline, North to the fence intersection, measures 529 feet.

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 2 1/2" brass cap on a 1 1/4" by 30" galv. iron pipe 24" in ground and surrounded with a mound of earth.

Set a steel fence post 3' West of corner with a Witness Corner sign attached.

New bearing objects:

- A 5/8" x 30" iron pin bears N 26 1/2°W - 34.4'
- A 5/8" x 30" iron pin bears N 60°W - 37.0'
- A 5/8" x 30" iron pin bears S 49 1/2°W - 42.3'
- A 5/8" x 30" iron pin bears S 03°W - 48.0'

All pins are capped with a 1 1/2" yellow plastic cap marked "W.R. WELLS, PLS 1106". Bearing Object signs are wired to each pin.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

expires 12-31-94

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

RECEIVED BY

Umatilla County Surveyor

Date 6-93

Rec'd By KR

No. 93-43-B

★ GPO-788-276