OREGON CORNER RESTORATION FORM

Section 2 Township 5N Range

Umatilla Date: County May 22, 2012

Condition Report Only Corner Designation:

5N36C17 Not found

36E


Remonumented Χ Quarter corner common to sections 2 and 3, T5N, R36E, Unrecorded

W.M., Umatilla County, Oregon. Surveyed in Referenced out

Previous Renewals / Surveys, etc.

Corner was originally set by Odell and Lewis under contract No. 110 dated February 7, 1865. Their record reads: Set 1/4 Sec. post. Drove charred stake, dug pits and raised mound as per instructions.

Monument and Accessories found: (condition and source) None. This point falls in a plowed field.



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)

Set a 1 1/2" x 30" galvanized iron pipe with a 2 3/8" brass cap stamped as shown in the diagram above 2 feet below the surface of the plowed field. I calculated the corner point on the section line by using twice the latitude between the south section corner and the railroad tie at the South 1/16th corner.

For references, I set four 5/8" by 24" iron rebars with 1 1/8" orange plastic caps stamped WTS and 56295LS as described below 2 feet below the surface of the plowed field:

an iron rebar bears N49°05'10"W, 25.92 feet;

an iron rebar bears N44°33'35"E, 24.54 feet;

an iron rebar bears S48°52'02"E, 24.73 feet;

an iron rebar bears \$43°26'03"W, 25.82 feet;

The monument was set and references were tied using Trimble R7/R8 RTK GPS.

Location and comments Compass Declination

NAD 83/1991 State Plane Coordinate

Oregon North Zone

Rec'd By: A. Oles

N = 836464.64 ift

E = 8764679.27 ift Firm / Agency

Witness Tree Surveying

RECEIVED BY: Address Umatilla County Surveyor

6/5/2012

12-088-C

P.O. Box G

Pilot Rock, Or. 97868

Party Chief

Stephen K, Haddock

REGISTERED **PROFESSIONAL** LAND SURVEYOR

Surveyors Seal

OREGON JULY 9, 2001 TEN K. HADDOCK

RENEWAL DATE 6-30-13