History of original corner establishment:

Index No. Q-2 DIAGRAM SEC 19 SW1/16 T 55 R31E W.M.

No record of subsequent remonumentation found in County Records . Description of corner evidence found:

None

None

Description of monument and accessories I established to perpetuate the original location of this corner

At the corner position a 2 inch by 30 inch iron pipe, with brass cap marked as shown, was set 29 inches in the ground and surrounded with a mound of stones to the cap.

Set steel fence posts South and West of corner on property line and attached signs 54-2 and 54-9. Established 2 new BT: A 11" red fir bears N86°E 116.2 ft.scribed SW 1/16 S 19BT.

A 7½ " Tamarack bears N35°W 41.9 ft.scribed SW 1/16 S 19BT.

New BT's have lower blaze scribed BT with a brass washer stamped PLS 1106 nailed to it. New BT's have 54-3 and 54-4 signs attached and a 6" red band painted around them above blaze. Location poster on west side of road 251+ East of corner.

NOTE: This corner was established in error in 7/79 and bearing trees established. When the corner was established in its true position, scribing and signs were removed from one BT referencing the erroneous position. From the correct corner position: A  $9\frac{1}{2}$ " red firbears S89°E 87.8 ft. with open bloze. Used steel tape and magnetic compass with  $19\frac{1}{2}$ ° east declination. Measured to center of Bts.

See map of survey

This corner set

August 12, 1979

Witnesses:

Greg Flower L.S.I.T.

**Brent Reynolds** 

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

T55 R316 SW1/6 519 1979 PLS 1106

County Surveyor .... County of Umatilla Oregon , I hereby certify that the within instrument was filed in this office

RECEIVED BY

Umatilla County Surveyor

Rec'd By

· GPO 796.333

Form R6-7100-57 (9/71)