
History of original corner establishment:

None



No record of subsequent remonumentation found in County Records .

None

Description of monument and accessories I established to perpetuate the original location of this corner

At the corner position a 2 inch by 30 inch iron pipe, with brass cap marked as shown, was set 18 inches in the ground and surrounded with a mound of stones to the cap.

Set steel fence post South and East of corner on property line and attached signs 54-2 and 54-9.

Established 2 new BT's: A 11" red fir bears N54°E 5.9 ft. scribed CN 1/16 S 30 BT.

A $8\frac{1}{2}$ " red fir bears S52 $\frac{1}{2}$ °E 11.6 ft. scribed CN 1/16 S 30 BT.

BT's have lower blaze scribed BT with a brass washer stamped PLS 1106 nailed to it.

BT's have 54-3 and 54-4 signs attached and a 6" red band painted around them above blaze.

See map of survey This corner set August 21, 1979	PROFESSIONAL LAND SURVEYOR	T55R3IE
Witnesses: Greg Flowers L.S.I.T. Brent Reynolds	Willia R. Wells	CN 16 530
	OREGON JULY 22, 1977 WILLIAM R. WELLS 1106	1979 PLS1106
Office of County Surveyor State of Oregon , I hereby certififor record on the		office

(DEPUTY)

RECEIVED BY

Imatilla County Surveyor

hate Gept. 4, 1979 hee'd By M. Hughes

Form R6-7100-57 (9/71)

(COUNTY OFFICIAL)

⇒ GPO 796-333

NOTE: This corner was erroneously established in 7/79 and bearing trees established. When the corner was established in its true position, scribing and signs were removed from BT's referencing the erroneous position. From the correct corner position: A 11½" red fir bears S86°E 227.± feet with open blaze. A 11" red fir bears S78°E 210± feet with open blaze.