
History of original corner establishment: None



No record of subsequent remonumentation found in County Records .

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner

At the corner position a 2 inch by 30 inch iron pipe, with brass cap marked as shown, was set 24 inches in the ground and surrounded with a mound of stones to the cap.

Set steel fence post on property line North of corner and attached signs 54-2 and 54-9.

Established two (2) new BT's: A 8" red fir bears S65°E 9.7 ft. scribed C4 S 30 BT.

A 10" red fir bears S8°E 17.1 ft. scribed C4 S 30 BT.

BT's have a lower blaze scribed BT with a brass washer stamped PLS 1106 nailed to it.

BT's have 54-3 and 54-4 signs attached and a 6" red band painted around them above blaze.

Used steel tape and magnetic comoass with See map of survey This corner set August 21, 1979 Witnesses: Greg Flowers, L.S.I.T. Brent Reynolds	PROFESSIONAL LAND SURVEYOR
	Willia R. Wells C'4 930
	OREGON JULY 22, 1977 WILLIAM R. WELLS 1106
Office of County Surveyor State of Oregon , I hereby certify	County of Umatilla that the within instrument was filed in this office
for record on the day of	
(COUNTY OFFICIAL)	RECEIVED BY
	Umatilla County Surveyof
그리아 아이는 그는 얼마나 하는데 하다.	Date Sept 4, 1979 -

Form R6-7100-57 (9/71)

NOTE: This corner was erroneously established in 7/79 and bearing trees established when the corner was established in its true position, scribing and signs were removed from BT's referencing the erroneous position. From the correct corner position: A 13" red fir bears N $68\frac{1}{2}$ °E 177'+w/open blazes. A $II\frac{1}{2}$ " red fir bears N85°E 156'+w/open blazes.

No. Q-1164-B