CERTIFIED RECORD OF LAND CORNER MONUMENTATION

200 P 5 0 V	200340
History of original corner establishment: 1882, George S. Pershin, U.S. Deputy Surveyor, while subdividing 1/	T. 5 S., R. 33 E. '4 corner of sections 19 & 20
the township under G.L.O. Contract No. 430 established the corner	DIAGRAM
as follows: Set a basalt Stone 17 X 10 X 5 ins 12 ins in ground for 1/4 sec. co	
marked 1/4 S on West Side raised mound of stone alongside	1/4
1984, David H. Krumbein, LS 933, (CS# 84-159-R) did not find any	S19 S20
evidence. By Proportionate Method	
Set a 2 1/2" dia. Brass Cap on a 2 1/2" X 30" galvanized pipe 15" in the ground and a mound of stones around Brass Cap.	1 1
From which scribed the Bearing Trees. A 12" dia. Ponderosa Pine bears N 48" E, 15.9 feet scribed 1/4 S20 E	
A 8" dia. Ponderosa Pine bears N 39" W, 25.1 feet scribed 1/4 S19 B	T .
1995, The Bureau of Land Management while computing geodetic coordii Land Survey Corners discover that Krumbein used an incorrect record in proportioned the corner.	
Description of corner evidence found:	
Found Krumbein's erroneously established corner as described in the colono evidence of the original stone was found.	unty records.
Description of monument and accessories I established to perpetuate the	
original location of this corner:	· ·
Set at proportionate distance a 2 1/2" diameter by 30" long aluminum pipe, with 3 1/4" diameter aluminum cap, 18" in the ground, with white SURV-KAP magnetic 1/2"	\$61
18" in the ground, with white SURV-KAP magnetic (\$\beta\$ 1/reference set in the bottom of the hole, surrounded by	
a rock mound 2 feet in diameter by 1 feet high, in a	\$20
North-South fenceline, marked as shown, from which:	2308
17" Ponderosa Pine bears S 87 3/4° E, 26.6 feet, scribed	
1/4 520 B1. 12" Ponderosa Pine bears S 41 1/2" E, 58.3 feet, scribed "1/4 S20" "BT". 19" Ponderosa Pine bears S 10 3/4" W, 47.9 feet, scribed "1/4 S19" "BT". 11" Ponderosa Pine bears N 62 1/4" W 40.1 feet with	
"1/4 S19" "BT". 11" Ponderosa Pine bears N 62 1/4" W, 40.1 feet, with	
scribing visible on partially healed blaze	
The 1/4 corner of sections 19 and 20, erroneously established by Krumbein in 1984, bears S 86°37′37″ W, 19.43 feet. Monumented with 2 1/2″ diameter iron pipe with a 2 1/2″	
diameter brass cap firmly set, in a mound of stones, with brass cap marked and witnessed as described in the county records.	
As per the direction of David H. Krumbein, Umatilla County Surveyor, I remove the 1984 monument and destroy the marks	
on the 1984 NE BT.	
The new bearing trees are double blazed and have a 3/4" diameter brownsher stamped "RLS 2308" nailed to the lower blaze by the "BT" scrib	ina.
DATUM: NAD83(1991) Oregon High Accuracy Reference Network	9.
No. Latitude Longitude in International Feet No. Latitude Longitude Northina(Y) Eas	sting(X)
200340 45°07′12.14254″ N. 118°45′28.53882″ W. 534705.326′ 8651	721.703'
Work Performed By: David A. Schlaich (RLS 2308) REGIST PROFES:	
Witnessed Rv: Matthew Duffy	RVEYOR
Magnetic Declination: 19 1/2 East Date: September 26, 2002	1. COD = A
The state of	schlaut
OREG JULY 16,	
DAVID A. 3	
RENEWAL DATE	: 06/30/2004
Office of	
State of, I hereby certify that the within instrument was filed in	n this office
for record on the day of, 20,	
(COUNTY OFFICIAL) by	

Form R6-7100-57 (9/71)