Point falls in open brushy area near bottom of ravine. Suspect local magnetic attraction is pulling needle  $\pm$ 15°W, all bearings shown here are with declination set to N15°E, typical for the Township. Bearings taken with Silva hand compass and distances measured with a steel tape.

# OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 850622.80

E = 8785499.56

**COMPASS DECLINATION: 15° East** 

**SURVEYORS' SEAL:** 

FIRM: HDJ Design Group

5 N. Colville, Suite 200 Walla Walla WA 99362

WITNESSES: Mark F. Wendover

Thomas J. Boshart Felipe G. Hernandez OREGON JUNE 30, 1997 GREG E. FLOWERS 02820LS

REGISTERED PROFESSIONAL

LAND SURVEYOR

RENEWS 12/31/15

06/29/2015

## **OREGON CORNER RESTORATION FORM**

COUNTY: Umatilla DATE: 7/22/2014

**CORNER DESIGNATION:** R-9, Section Corner common to Sections 20, 21, 28 and 29 Township 6 North, Range 37 East, W.M.

#### PREVIOUS RENEWALS/SURVEYS ETC:

Originally surveyed by George Williams, Contract No. 176, dated July 20, 1872. His notes state "Set stone  $4 \times 24 \times 30$ , mound and pits for the cor. of Secs 20, 21, 28 and 29.

Surveyor Paul W.P. Tomkins noted in his September 28, 1992 survey, shown on Umatilla County Survey record of surveys 92-122-B, "Held fence corner as best evidence of section corner, searched for stone, not found."

Surveyor Paul W.P. Tomkins noted in his April 9, 2001 survey, shown on Umatilla County Survey record of surveys 01-64-B, "Found survey tack in fence corner, S.E. corner, Section 20, per survey 92-122-B.

Surveyor Paul W.P. Tomkins noted in his January 8, 2005 survey, shown on Umatilla County Survey Record of Plats 2005-02, "Found survey tack in fence corner, S.E. corner, Section 20, per survey 92-122-B.

Surveyor Paul W.P. Tomkins noted in his October 14, 2008 survey, shown on Umatilla County Survey Record of Plats 2008-29, "Found survey tack in fence corner, S.E. corner, Section 20, per survey 92-122-B.

#### MOUNUMENT AND ACCESSORIES FOUND:

Found ancient rotted 4 x 4 post buried 1 foot NE of post at corner of fence running North, South and West. A nail and flagging are set in the top of fence corner post. No other evidence found.

## MOUNUMENT MARKING DETAIL:

LS 02820

T6N R37E

S20 S21

S29 S28

2014

#### MOUNUMENT AND ACCESSORIES SET:

Set 1½" galvanized iron pipe with a 2½" brass cap, 6" SW of ancient post and 6" NE of fence corner with top 4"exposed, from which:

A 5/8" x 30" iron rebar with yellow plastic cap "TLS-HDJ" bears N32°E, 37.70 feet distance.

A 5/8" x 30" iron rebar with yellow plastic cap "TLS-HDJ" bears N45°W, 49.00 feet distance.

A 5/8" x 30" iron rebar with yellow plastic cap "TLS-HDJ" bears S19°E, 22.40 feet distance.

A 5/8" x 30" iron rebar with yellow plastic cap "TLS-HDJ" bears S67°W, 36.20 feet distance, with tag on fence post over this rebar.

Set witness tag on T-Post bearing N68°W, 1.50 feet distance.

### **LOCATION AND COMMENTS:**