OREGON CORNER RESTORATION FORM

COUNTY: Umatilla

DATE: 12/19/2014

CORNER DESIGNATION: V-13, Corner for Sections 27, 28, 33 and 34, Township 6 North,

Range 37E, W.M.

PREVIOUS RENEWALS/SURVEYS ETC:

Originally surveyed by A.H. Simmons for Deputy Surveyor George Williams under his contract No. 176 dated October 23, 1872; his notes state "Set post and stone mound and pits for corner of Sections 27, 28, 33 & 34.

MOUNUMENT AND ACCESSORIES FOUND:

No evidence found.

MOUNUMENT MARKING DETAIL:

T6N R37E

S27 S28

S33 S34

12/2014

LS 02820

MOUNUMENT AND ACCESSORIES SET:

At the surveyed position, set a 2 ½ inch brass cap on 1½" galvanized iron pipe, 6" above ground marked corner of sections 27,28, 33 and 34, T6N,R37E by LS 02820 on 12/2014, From which: Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears N43°W, 15.00 feet. Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears S42°W, 18.00 feet. Set a 5/8" iron rebar with yellow plastic cap marked "TLS=HDJ" bears N48°E, 10.00 feet. A six inch diameter fir tree bears S27°E 29.60 feet blazed, scribed and tagged accordingly.

LOCATION AND COMMENTS:

Corner falls on steep west facing slope with three foot tall shrubs. Bearings taken with Silva hand compass and distances measured with a steel tape.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 845614.87

E = 8790814.13

COMPASS DECLINATION: 15° East

SURVEYORS' SEAL:

FIRM:

HDJ Design Group

5 N. Colville, Suite 200 Walla Walla WA 99362

WITNESSES: Joseph R. Latimer

Corey A. West

REGISTERED PROFESSIONAL LAND SURVEYOR

JUNE 30, 1997 GREG E. FLOWERS 02820LS

RENEWS 12/31/15

06/19/10/5

15-063-C