OREGON CORNER RESTORATION FORM

COUNTY: Umatilla

DATE: 01/08/2015

CORNER DESIGNATION: V-5, Corner for Sections 29, 30, 31 and 32, Township 6 North, Range 37E, W.M.

PREVIOUS RENEWALS/SURVEYS ETC:

Originally surveyed by A.H. Simmons for Deputy Surveyor George Williams under his contract No. 176 dated October 23, 1872; his notes state "Set post, mound and pits for corner to Sections 28, 29, 32 & 33.

MOUNUMENT AND ACCESSORIES FOUND:

No evidence found.

MOUNUMENT MARKING DETAIL:

T6N R37E

S30 S29

S31 S32

1/2015

LS 02820

MOUNUMENT AND ACCESSORIES SET:

At the surveyed position, set a 2 ½ inch Brass Cap on 1½" galvanized iron pipe, three inches above ground marked corner of sections 28,29, 32 and 33, T6N,R37E by LS 02820 on 12/2014, from which:

Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears N40°W, 10.00 feet. Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears N56°E, 10.00 feet. Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears S48°W, 12.00 feet. Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears S21°E, 16.00 feet.

LOCATION AND COMMENTS:

Track road approximately 120 feet N to NE, no trees, good dirt. Bearings taken with Silva hand compass and distances measured with a steel tape.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 845202.75

E = 8780412.78

COMPASS DECLINATION: 15° East

SURVEYORS' SEAL:

FIRM:

HDJ Design Group

5 N. Colville, Suite 200

Walla Walla WA 99362

WITNESSES: Joseph R. Latimer

Corey A. West

REGISTERED PROFESSIONAL LAND SURVEYOR

JUNE 30, 1997 GREG E. FLOWERS 02820LS

RENEWS 12/31/15

06/29/2015

15-063- C