OREGON CORNER RESTORATION FORM

COUNTY: Umatilla

DATE: 12/31/2014

CORNER DESIGNATION: V-9, Corner for Sections 28, 29, 32 and 33, Township 6 North,

Range 37E, W.M.

PREVIOUS RENEWALS/SURVEYS ETC:

Originally surveyed by A.H. Simmons for Deputy Surveyor George Williams under his contract No. 176 dated October 23, 1872; his notes state "Set stone 15"x17"x24" monument and pits for corner to Sections 28, 29, 32 & 33.

MOUNUMENT AND ACCESSORIES FOUND:

No evidence found.

MOUNUMENT MARKING DETAIL:

T6N R37E

S29 S28

S32 S33

12/2014

LS 02820

MOUNUMENT AND ACCESSORIES SET:

At the surveyed position, set a 2 ½ inch brass cap on 1½" galvanized iron pipe, 3" above ground marked corner of sections 28,29, 32 and 33, T6N,R37E by LS 02820 on 12/2014, from which: Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears N34°W, 13.00 feet. Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears N46°E, 12.00 feet. Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears S44°W, 15.00 feet. Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears S38°E, 10.00 feet.

LOCATION AND COMMENTS:

Bearings taken with Silva hand compass and distances measured with a steel tape.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 845423.66

E = 8785632.51

COMPASS DECLINATION: 15° East

SURVEYORS' SEAL:

REGISTERED PROFESSIONAL

LAND SURVEYOR

FIRM:

HDJ Design Group

5 N. Colville, Suite 200

Walla Walla WA 99362

WITNESSES: Joseph R. Latimer

Corey A. West

JUNE 30, 1997 GREG E. FLOWERS 02820LS

02820LS RENEWS 12/31/15

RENEWS 12/31/15 06/29/20/5

15-063-C