# **OREGON CORNER RESTORATION FORM**

**COUNTY:** Umatilla

DATE: 07/09/2014

**CORNER DESIGNATION:** X-17, Quarter Corner for Sections 34 and 35, Township 6 North, Range 37E, W.M.

# PREVIOUS RENEWALS/SURVEYS ETC:

Originally surveyed by A.H. Simmons for Deputy Surveyor George Williams under his contract No. 176 dated October 23, 1872; his notes state "Set stone 18"x15"x10" with mound of rock for quarter sections 34 & 35.

# MOUNUMENT AND ACCESSORIES FOUND:

No evidence found.

### **MOUNUMENT MARKING DETAIL:**

T6N 14 S34 S35 R37E 2014 LS 02820

#### MOUNUMENT AND ACCESSORIES SET:

At the surveyed position set a 2½" brass cap on 1½ x 30" galvanized iron pipe, marked quarter corner for sections 34 and 35, T6N, R37E by LS 02820 2014. From which:

Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears N63°W, 41.10 feet.

Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears N46½°E, 32.60 feet.

Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears S49°W, 31.30 feet.

Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears S64°E, 48.20 feet.

### **LOCATION AND COMMENTS:**

Bearings taken with Silva hand compass and distances measured with a steel tape.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 843293.11

E = 8795999.45

**COMPASS DECLINATION:** 15° East

**SURVEYORS' SEAL:** 

REGISTERED PROFESSIONAL

LAND SURVEYOR

FIRM:

HDJ Design Group

5 N. Colville, Suite 200 Walla Walla WA 99362

WITNESSES: Mark F. Wendover

Felipe G. Hernandez

OREGON JUNE 30, 1997 GREG E. FLOWERS

RENEWS 12/31/15

06/29/2015