OREGON CORNER RESTORATION FORM

COUNTY: Umatilla

DATE: 01/08/2015

CORNER DESIGNATION: X-5, Quarter Corner for Sections 31 and 32, Township 6 North, Range 37E, W.M.

PREVIOUS RENEWALS/SURVEYS ETC:

Originally surveyed by A.H. Simmons for Deputy Surveyor George Williams under his contract No. 176 dated October 23, 1872; his notes state "Set post in mound and pits for corner quarter sections 31 & 32.

MOUNUMENT AND ACCESSORIES FOUND:

No evidence found. Point landed in farmed field.

MOUNUMENT MARKING DETAIL:

LS 02820 T6N R37E S31|S32 1/4 01/2015

MOUNUMENT AND ACCESSORIES SET:

At the surveyed position, set a 2½ inch brass cap on 1½" galvanized iron pipe, marked quarter corner for sections 31 and 32, T6N, R37E by LS 02820 01/2015. Set 22 inches below ground, from which:

Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" 20" below ground bears N. 46° W., 15.00 ft.

Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" 20" below ground bears N. 49° E., 15.00 ft.

Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" 20" below ground bears S. 55° W., 12.00 ft.

Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" 20" below ground bears S. 28° E., 10.00 ft.

LOCATION AND COMMENTS:

Did not set witness post due to location in farmed field. Bearings taken with Silva hand compass and distances measured with a steel tape.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 842598.20

E = 8780492.64

COMPASS DECLINATION: 15° East

SURVEYORS' SEAL:

REGISTERED PROFESSIONAL

LAND SURVEYOR

FIRM:

HDJ Design Group

5 N. Colville, Suite 200

Walla Walla WA 99362

WITNESSES: Joseph R. Latimer

Corey A. West

02820LS

RENEWS 12/31/15

15-063-C

6N37E X-5.DOC