Subdivisions of T. 1 N., R. 30 E.

	Chains		T
		drove charred stake and raised mound of earth with	
		trench and pits as per instructions. This line crosses	
	11	several small ridges and hollows running N.E. into	
	13	big hollow before noted.	
)	4 4 4	Land, rolling prairie.	
		Soil, good, 2nd rate.	
	19	East on a random line between secs. 21 and 28.	
		Var. 19° E.	
5%	40.00	Set temporary qr. sec. post and descend.	
	80.00	Intersect N. and S. line, 16 lks. South of corner to secs.	Lev
		21, 22, 27 and 28.	
		S. 89° 53' W., on true line between secs. 21 and 28.	
	11.00	To hollow and ascend.	
	40.00	Set quarter sec. post, drove charred stake and raised	
)		mound of earth with trench and pits as per instructions.	
	42.00	To summit and descend.	+50
	63,00	Cross hollow and ascend.	ľ
	80.00	The corner to secs. 20, 21, 28 and 29.	
		Land, rolling prairie.	
		Soil, 2nd rate.	
	ŀ		
		North between secs. 20 and 21.	
	40.00	Set a post for quarter section corner, drove charred	
		stake and raised mound of earth with trench and pits	
		as per instructions.	Ì
	80.00	Set a post for corner to secs. 16, 17, 20 and 21. Drove	
		a charred stake and raised mound of earth as per	
		instructions.	
J		Land, gently rolling prairie.	
		Soil, good, 2nd rate.	
	2	East on a random line between secs. 16 and 21.	1
		Var. 19° 55' E.	
710		Commence descend from post.	1
	40.00	A SECOND CONTROL OF THE CONTROL OF T	110
	40.00	Set temporary quarter sec. post.	110