Subdivisions,	T.	2	N.,	R.	34	E.
---------------	----	---	-----	----	----	----

		Subdivisions, T. 2 N., R. 34 E.
	Chains 40.00	Set temporary ½ Sec. corner.
	79.84	Intersected N. & S. line at corner.
		West on true line.
	15.50	Enter field, bears N & S.
	39.92	Set post for \( \frac{1}{4} \) Sec. corner, from which
		A Balm, 24 ins. bears N.45° E. 4 lks.
	41.00	Leave field and enter river to
	79.84	To corner.
		Land, level. Soil, 1st & 2nd rate. Bottom land
		subject to inundation.
	1 1000	
		West on random bet. secs. 6 & 7.
	60.00	Set temporary \(\frac{1}{4}\) Sec. corner.
	79.90	Intersected N. & S. line 14 S. of cor.
		S.89° 54' E. on true line.
	39.90	Set stone 15 x 14 x 8 for \frac{1}{4} Sec. cor.
į.	60.00	Umatilla River, 250 lks., flows S.W.
	79.90	To corner.
14		Land, level. Soil, 1st & 2d rate.
	- 1	North on random between secs. 5 & 6.
	40.00	Set temporary 1 Sec. corner.
	80.14	Intersected N. boundary 20 links W. of corner.
		S.00° 09' W. on true line.
	40.14	Set stone 18 x 12 x 12 for \frac{1}{4} Sec. corner.
	73.00	Umatilla River, flows S.W.
	80.14	To corner.
		Land, rolling. Soil, 1st and 2nd rate.
		7
k.		June 8, 1871.
	3"	Notes T class that our company that have been been been been been been been be
		Note: I find that any corners that have been heretofore
		set on any portion of the Indian Reservation have been
		destroyed, and all the lines in my work closed so I
		had to rerun and establish all corners anew.