...

~~	bdivisions, T. 3 N., R 30 E.
Chains	
3.	West, on a true line between Secs. 13 & 24.
40.09	Set a post for quarter section corner, drove a charred
wi e	stake and raised a mound of earth, with trench and
1 20	pits, as per instructions.
80.18	The corner to Secs. 13, 14, 23 & 24.
	Soil, good 2nd rate.
	Land, level and rolling prairie.
	haid, level and lolling platite.
698 69	North between Secs. 13 & 14.
40.00	The state of the s
40.00	Set a post for quarter section corner. Drove a charred
	stake and raised mound of earth, as per instructions.
80.00	Set a post for corner to Sections 11, 12, 13 & 14. Drove
	a charred stake and raised a mound of earth with trench
95	and pits as per instructions.
1 4, 4	Land, nearly level. Prairie.
	Soil, good 2nd rate.
	East on a random line between Secs. 12 & 13.
	Variation 9° 45' E.
40.00	Set a temporary quarter sec. post.
79.56	Intersect Guide Meridian 24 links South of post; corner
	secs. 12 & 13.
	S.89°50' W. On true line between Secs. 12 & 13.
39.78	Set a post for quarter section corner. Drove a charred
00.10	stake and raised a mound of earth with trench & pits
	The Company of the Co
100	as per instructions.
79.56	The corner to sections 11, 12, 13 & 14.
	Land, rolling prairie.
- 6-	Soil, good, 2nd rate.
F 19	
	North between Secs. 11 & 12.
40.00	Set a post for quarter section corner, drove a charred
	stake and raised a mound of earth with trench and pits,
	as per instructions.
	n D D D
	Chains 40.09 80.18 40.00 80.00 79.56