	Subdivision Lines Township 3 N., R. 31 E. W. M.
Chains 13.00	Road to Walla Walla (E. & W.)
40.00	Set charred stake with mound, trench and pits as per
	insts. for ½ sec. corner.
80.00	Set charred stake with mound, trench and pits as per
	insts. for corner to Secs. 28 & 29, 32 & 33.
	Var. 20°20' E.
	Soil, good.
	S. 89°18' E. on random between Secs. 28 & 33.
40.00	Set Temp. 2 sec. post.
79.54	Intersect sec. line at post corner to Secs. 27 & 28,
	33 & 34.
	N. 89°18' W. on true line between Secs. 28 & 33.
39.77	Set charred stake with mound, trench and pits as per
	insts. for \(\frac{1}{4}\) sec. corner.
79.54	Corner to Secs. 28 & 29, 32 & 33.
20	Soil, 2nd rate.
	North on line between Secs. 28 & 29.
40.00	Set charred stake with mound, trench and pits as per
40.00	
40.00	Set charred stake with mound, trench and pits as per
NO CONTRACTOR	Set charred stake with mound, trench and pits as per insts. for ½ sec. corner. Set charred stake with mound, trench and pits as per insts. for corner to Secs. 20 & 21, 28 & 29.
NO CONTRACTOR	Set charred stake with mound, trench and pits as per insts. for ½ sec. corner. Set charred stake with mound, trench and pits as per insts. for corner to Secs. 20 & 21, 28 & 29. Var. 19°30' E.
NO CONTRACTOR	Set charred stake with mound, trench and pits as per insts. for ½ sec. corner. Set charred stake with mound, trench and pits as per insts. for corner to Secs. 20 & 21, 28 & 29.
NO CONTRACTOR	Set charred stake with mound, trench and pits as per insts. for ½ sec. corner. Set charred stake with mound, trench and pits as per insts. for corner to Secs. 20 & 21, 28 & 29. Var. 19°30' E.
NO CONTRACTOR	Set charred stake with mound, trench and pits as per insts. for \(\frac{1}{4} \) sec. corner. Set charred stake with mound, trench and pits as per insts. for corner to Secs. 20 & 21, 28 & 29. Var. 19°30' E. Soil, 2nd rate.
80.00	Set charred stake with mound, trench and pits as per insts. for \(\frac{1}{4} \) sec. corner. Set charred stake with mound, trench and pits as per insts. for corner to Secs. 20 & 21, 28 & 29. Var. 19°30' E. Soil, 2nd rate. S. 89°18' E. on random between Secs. 21 & 28. Set Temp. \(\frac{1}{4} \) post. Int. sec. line 58 lks. North of corner to Secs. 21
80.00	Set charred stake with mound, trench and pits as per insts. for \$\frac{1}{4}\$ sec. corner. Set charred stake with mound, trench and pits as per insts. for corner to Secs. 20 & 21, 28 & 29. Var. 19°30' E. Soil, 2nd rate. S. 89°18' E. on random between Secs. 21 & 28. Set Temp. \$\frac{1}{4}\$ post. Int. sec. line 58 lks. North of corner to Secs. 21 & 22, 27 & 28.
80.00 40.00 79.86	Set charred stake with mound, trench and pits as per insts. for \(\frac{1}{4} \) sec. corner. Set charred stake with mound, trench and pits as per insts. for corner to Secs. 20 & 21, 28 & 29. Var. 19°30' E. Soil, 2nd rate. S. 89°18' E. on random between Secs. 21 & 28. Set Temp. \(\frac{1}{4} \) post. Int. sec. line 58 lks. North of corner to Secs. 21 & 22, 27 & 28. N. 89°54' W. on true line between Secs 21 & 28.
80.00	Set charred stake with mound, trench and pits as per insts. for \$\frac{1}{4}\$ sec. corner. Set charred stake with mound, trench and pits as per insts. for corner to Secs. 20 & 21, 28 & 29. Var. 19°30' E. Soil, 2nd rate. S. 89°18' E. on random between Secs. 21 & 28. Set Temp. \$\frac{1}{4}\$ post. Int. sec. line 58 lks. North of corner to Secs. 21 & 22, 27 & 28. N. 89°54' W. on true line between Secs 21 & 28. Set charred stake with mound, trench and pits as per
40.00 79.86	Set charred stake with mound, trench and pits as per insts. for \(\frac{1}{4} \) sec. corner. Set charred stake with mound, trench and pits as per insts. for corner to Secs. 20 & 21, 28 & 29. Var. 19°30' E. Soil, 2nd rate. S. 89°18' E. on random between Secs. 21 & 28. Set Temp. \(\frac{1}{4} \) post. Int. sec. line 58 lks. North of corner to Secs. 21 & 22, 27 & 28. N. 89°54' W. on true line between Secs 21 & 28. Set charred stake with mound, trench and pits as per insts. for \(\frac{1}{4} \) sec. corner.
80.00 40.00 79.86	Set charred stake with mound, trench and pits as per insts. for \(\frac{1}{4} \) sec. corner. Set charred stake with mound, trench and pits as per insts. for corner to Secs. 20 & 21, 28 & 29. Var. 19°30' E. Soil, 2nd rate. S. 89°18' E. on random between Secs. 21 & 28. Set Temp. \(\frac{1}{4} \) post. Int. sec. line 58 lks. North of corner to Secs. 21 & 22, 27 & 28. N. 89°54' W. on true line between Secs 21 & 28. Set charred stake with mound, trench and pits as per insts. for \(\frac{1}{4} \) sec. corner. Corner to Secs. 20 & 21, 28 & 29.
40.00 79.86	Set charred stake with mound, trench and pits as per insts. for ½ sec. corner. Set charred stake with mound, trench and pits as per insts. for corner to Secs. 20 & 21, 28 & 29. Var. 19°30' E. Soil, 2nd rate. S. 89°18' E. on random between Secs. 21 & 28. Set Temp. ½ post. Int. sec. line 58 lks. North of corner to Secs. 21 & 22, 27 & 28. N. 89°54' W. on true line between Secs 21 & 28. Set charred stake with mound, trench and pits as per insts. for ½ sec. corner.