Subdivisional	Lines	of	Township	3	North,	Range	36	E.	W.	M.
---------------	-------	----	----------	---	--------	-------	----	----	----	----

*	T May A	Subdivisional Lines of Township 3 North, Range 36 E. W. 1	M.
	Chains	Pine, 24 in diam. prs. S. 68° E. 50 lks. dist.	
	739 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 -	Fir, 10 in diam. brs. S. 74° W. 95 lks. dist.	
	53.00	Road, E. & W. to timber.	*
	75.22	The cor. to Sec. 3, 4, 9 and 10.	
(1)		Land: Surface, hilly; Soil, 2nd and 1st rate: has been	
		good timber, but a large and the best part of it is	
- 59		cut and used and much has been wastefully destroyed.	
E 69		Oct. 19th 1878.	-
	;	West on a true line between Sec. 4 and 9.	
94			
	40.00	Va. 21° East.	
*	40.00	Set tamarack post for & sec. cor.	-10
		Pine, 28 in diam. brs. East 72 lks. dist.	
		. Tama., 13 in diam. brs. N. 46° W. 27 lks. dist.	
*	46.00	Brook, 12 lks. wide, course NW.	-20
$\cap$	60.50	Road, N. & S. to timber	<b>‡15</b> 6
	68.50	Road, NE. & SW. to timber.	
100	80.00	Set fir post in shallow ravine for cor. to Sec. 4, 5, 8	
	-	& 9	
35	•**	. A fir, 34 in diam. brs. N. 40° E. 6 lks. dis.	
	•	. A fir, 14 in diam. brs. S. 64° E. 34 lks. dis.	
-	15. =	. A fir, 16 in diam. brs. S. 16° W. 46 lks. dis.	
	T <sub>e</sub> n.	A fir, 15 in diam. brs. N. 42° W. 50 lks. dis.	
		Land: Surface, hilly: Soil, 1st & 2nd rate; good timber	-
	B =600106	West of brook: East of brook, scattering fir, tama-	
		rack and pine. Some willow & other underbrush. Good	
	17 13	. grass in openings.	
$\cap$		North on a random line between Sec. 4 and 5.	
75		Va. 21°10' East.	
	40.00	Set post for temporary \( \frac{1}{4} \) sec. cor.	
	75.46	Intersected North Boundary 192 lks. East of cor. to Sec.	
		4 & 5, from which cor. I run	28
3.	5276	S. 1°22' East on a true line between Sections 4 and 5.	
	504	Va. 20° East.	m
8	15.50	Top of bluff.	<del> </del> 500
			puediti.

68

KILHAM 15674