	Chains 43.00	Leave undergrowth and timber and enter prairie	Fe
	80.02	The Cor. to Secs. 33, 34, 27 & 28	
	80.02	2 3 1 3 7 7 7 7 7	
(4		W. & mile rolling land, 2nd rate, E. & mile low wet ground, subject to overflow.	
	3.4	N. bet. Secs. 27 & 28	
	40.00	Set post for \(\frac{1}{4}\) Sec. Cor., in mound with trench and pits	
10		and deposited 1 pint charcoal, as per instructions.	
	80.00	Set post for Cor. to Secs. 21, 22, 27 & 28, in mound with	
		trench and pits and deposited 1 pint charcoal as per	
		instructions.	
		Soil; 3rd rate, producing grass. Land; rolling	3
		E. on random line bet. Secs. 22 & 27	
- 1	40.00	Var. 19° 45' E. Set post for temp. ½ Sec. Cor.	
	80108	Intersect N. and S. line, 6 lks. N. of the Cor. to Secs.	
8		22, 23, 26 & 27, from which Cor. I run	
		N. 89° 57' W. on true line bet. Secs. 22 & 27	
	40.04	Set post for \(\frac{1}{4} \) Sec. Cor. in mound with trench and pits	7
		and deposited 1 pint of charcoal, as per instructions.	
	80.08	The Cor. to Secs. 21, 22, 27 & 28	
*		Soil; 3rd rate, producing grass. Land; rolling.	ST TO STATE OF
	34.1	N. bet. 21 & 22	
	40.00	Set post for 2 Sec. Cor., in mound with trench and pits,	
	1 XISDS TOURS	and deposited 1 pint of charcoal, as per instructions.	
	80.00	Set post for Cor. to Secs. 15, 16, 21 & 22, in mound with) }#
	10 m 20 m 40 m 50 m 50 m 50 m 50 m 50 m 50 m 5	trench and pits and deposited 1 pint charcoal as per	
		instructions.	
		Soil; 3rd rate, producing grass.	
		Land; gently rolling.	
	w ng	E. on random line bet. Secs. 15 & 22	
	40.00	Set post for temp. \(\frac{1}{4}\) Sec. Cor.	
	79.70	Intersect N. and S. line, 18 lks. N. of the Cor. to Secs.	
	. 4	14, 15, 22 & 23, from which Cor. I run	
	3.	N. 89° 52' W. on true line bet. Secs. 15 & 22.	
	39.85	Set post for } Sec. Cor., in mound with trench and pits &	

....